




12.000 SERIES

MAIN SWITCHES

SPECIFICATIONS:

ELECTRICAL CHARACTERISTICS: 3A with resistive load 250~

CONTACT RESISTANCE: maximum of 10 miliohms with 1A DC.

INSULATION RESISTANCE: minimum de 1.000 megaohms.

DIELECTRIC WITHSTAND: 1000 V (rms) for 1 minute (minimum).



OPERATION TEMPERATURE: from 0°C to 55°C.

ACTUATOR: momentary stopping in the center.




REFERENCE - 12001

M# - FRAME
T2# - ACTUATOR




TERMINALS


E1 - faston 2,8 x 0,5 (standard)




E2 - faston 4,8 x 0,5



E3 - faston 6,3 x 0,8



P1 - screw



CONTACTS

S - STANDARD


3A with resistive load 250VAC

- COLORS



Note: Substitute # by the code of requested **color**.

A - blue **E** - red
B - white **F** - black - (standard)
C - yellow **G** - gray
D - green **H** - brown

CUT FOR FIT



BOX (OPTIONAL)



Note:
Include **CX** in the end of the code if you choose iron box and plastic cover.

SELECTION GUIDE

12001

Reference



frame
M#



actuator
T2#



terminal
E1
E2
E3
P1



contact
S



box
CX

CONNECTION DIAGRAM

